

Oil Field Environmental Incident Summary

Incident: 20150625144258 **Date/Time of Notice:** 06/25/2015 14:42

Responsible Party: HRC OPERATING, LLC

Well Operator: HRC OPERATING, LLC

Well Name: GREV 157-100-30B-31-2H

Field Name: MARMON

Well File #: 26118

Date Incident: 6/25/2015 **Time Incident:** 10:00

Facility ID Number:

County: WILLIAMS

Twp: 157 **Rng:** 100 **Sec:** 19 **Qtr:**

Location Description:

Submitted By: Chris Martinez

Received By:

Contact Person: Chris Martinez
1801 CALIFORNIA STREET
SUITE 3500
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	2	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/7/2015

Clean Up Concluded: 6/25/2015

Risk Evaluation:

No immediate risk to health or waterways. All contained on-site.

Areal Extent:

Potential Environmental Impacts:

No immediate risk to health or waterways. All contained on-site.

Action Taken or Planned:

Stuffing box rubbers replaced and will determine cause of pressure build-up prior to placing well back in service.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 6/25/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location within the dikes. NDIC retains oversight.